Serial No. 10/705,324

## IN THE SPECIFICATION

Page 1, lines 16-21 have been amended as follows:

2. When exposed to [[the]] sunshine for a long time, the clotheshorse made of plastic material will deform and become brittle whereby the <u>using useful</u> life of the clotheshorse is short. Thus, when not in use, the clotheshorse should be put in <u>a</u> room and shielded from sunlight. However, because it is difficult to detach the arms, the non-collapsed clotheshorse with a large overall size will occupy a great amount of space.

Page 4, line 23 through page 5, line 3 have been amended as follows:

With reference to Figs. 7-8, in another embodiment of the present invention, the arm ([[20']] 20a) has a ring (23) formed at the front end thereof. When two clotheshorses of the invention are mounted on the clothes-airing frame, a clothes bar ([[23]] 40) or a clothesline (not shown) can be attached between two opposed rings (23) of the two clothes bar (23) arms (20a) for hanging more clothes.

## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
□ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
COLOR OR BLACK AND WHITE PHOTOGRAPHS
GRAY SCALE DOCUMENTS
LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
Потиев.

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.